

### Crystal Setup File Parameters

Run Name: JSC3112803-20170109-002  
 Path: C:\Documents and Settings\Administrator\\*ÃæÃÜÊÃÏ¼p\12.8l  
 Print: All Operator:  
 Row A: Measured FL

Ref F: F @ ?  
 Run Start: 10-0»ÔÃ-2  
 Run Finish: 10-0»ÔÃ-2

S&A W2200 Rev: 6.5:

Start: A001 Stop: A030  
 Setup: JSC3112803C-20140803  
 Reference F: 12,800,000 Hz CL: 20.00 pF Power: 100.00 uW into 80.00 Ohms Measure: FL/T

	TEMP	FL	C0	RR	Q	C1	DLD2	FL	
A010<	90.02	1.3	2.834<	41	%608<	0.494<	5.081<	%12,800,01	20170109197
A010<	93.99	2.3<	2.828<	42	%596<	0.494<	5.326<	%12,800,02	20170109197
A010<	97.98	3.9<	2.832<	42	%603<	0.495<	5.639<	%12,800,05	20170109197
A014<	90.04	0.2	2.630	79	%840.	0.188<	7.665<	%12,800,00	20170109203
A014<	93.96	0.0	2.624	79	%842.	0.188<	7.351<	%12,800,00	20170109203
A014<	98.00	-0.2	2.630	78	%846.	0.188<	7.075<	%12,799,99	20170109203
A015<	90.00	0.3	2.635	71	%948.	0.186<	6.187<	%12,800,00	20170109193
A015<	94.00	0.3	2.627	71	%945.	0.186<	6.091<	%12,800,00	20170109193
A015<	98.02	0.2	2.633	71	%940.	0.186<	6.121<	%12,800,00	20170109193
A017<	89.99	-1.3	2.635	69	%981.	0.182	4.009<	%12,799,98	20170109202
A017<	93.99	-1.5<	2.628	70	%977.	0.182	4.950<	%12,799,98	20170109202
A017<	98.01	-1.8<	2.635	70	%975.	0.183	5.945<	%12,799,97	20170109202
A021<	90.02	0.9	3.888<	68	%691<	0.266<	1.404	%12,800,01	20170109198
A021<	94.02	0.9	3.881<	67	%696<	0.266<	1.443	%12,800,01	20170109198
A021<	98.00	0.8	3.888<	67	%693<	0.267<	0.998	%12,800,01	20170109198
A022<	90.03	-1.0	2.649	66	%987.	0.190<	2.482	%12,799,98	20170109206
A022<	93.99	2.3<	2.828<	42	%596<	0.494<	5.326<	%12,800,02	20170109206
A022<	98.02	0.2	2.633	71	%940.	0.186<	6.121<	%12,800,00	20170109206