

Crystal Setup File Parameters

Run Name: JSC1112801-20170527

Ref
Run Start: 27

Print: All Operator:

Run Finish: 27
S&A W2200 I

Row A: Measured FL

Row B: Measured FL

Start: B001 Stop: B110

Setup: JSC1112801

Reference F: 12,800,000 Hz CL: 20.00 pF Power: 100.00 uW into 25.00 Ohms Meas

	TEMP ; ¢C	FL ppm	CO pF	RR Ohms	Q k	C1 fF	DLD2 Ohms	FL Hz
		2.4	5.07	110.000		0.221	20.000	
		-2.4	2.73		630.000	0.119		
B044<	86.98	1.4	3.49	89.085	684.752	0.204	62.994< 12,800,01	2.0171E+10
B044<	91.99	1.9	3.51	80.897	752.791	0.204	74.320< 12,800,02	2.0171E+10
B044<	97.02	1.9	3.50	76.863	788.982	0.205	25.267< 12,800,02	2.0171E+10
B054<	87.00	1.3	3.43	63.185	901.002	0.218	9.169 12,800,01	fo2418
B054<	92.01	1.3	3.44	63.441	894.352	0.219	20.882< 12,800,01	fo2418
B054<	96.98	1.3	3.44	63.436	892.444	0.220	18.598 12,800,01	fo2418