

20170112009

### Crystal Setup File Parameters

Run Name: jsc311280h91-20170430

Print: All Operator:  
Row A: Measured FL

Row B: Measured FL

Ref F: F @ 1  
Run Start: 30-ËÄÖÅ-2  
Run Finish: 30-ËÄÖÅ-2

S&A W2200 Rev: 6.6

Start: B001 Stop: B050

Setup: JSC311280H91-TEMPH900168 921a-1021a

Reference F: 12,800,000 Hz CL: 20.00 pF Power: 100.00 uW into 25.00 Ohms Measure: FL/T

TEMP	FL	CI	CO	RR	Q	FL	DLD2	TEMP	FL	
! ¢C	ppm	fF	pF	Ohms	k	Hz	Ohms	! ¢C	ppm	
B030<	91.98	-0.10	0.246	2.11	83.8<	%602<	%12,799,99	20170112009	1.00	0.29
B030<	97.01	-0.17	0.246	2.09	80.1<	%630<	%12,799,99	20170112009	-3.00	0.19
B030<	102.00	0.00	0.247	2.10	80.7<	%623<	%12,799,99	20170112009		