

ARZ

Crystal Setup File Parameters

Run Name: JSC3112803-20170430-62

Ref F: F @ 1

Run Start: 30-EA0A-21
Run Finish: 30-EA0A-21

Print All Operator:
Row A: Measured FL

Row B: Measured FL

S&A W2200 Rev. 6.6

Start: B001 Stop: B070

Setup: jsc3112803-20120710 80-85-90

Reference F: 12,800,000 Hz CI: 20.00 pF Power: 100.00 uW into 25.00 Ohms Measure: FL/T

	TEMP i°C	FL ppm	C0 pF	RR Ohms	Q k	C1 pF	DLD2 Ohms	FL Hz	
B054<	80.02	0.09	2.332	83.11	859.44	0.174	10.78<	12,800,001	20170109083
B054<	85.02	0.18	2.337	82.93	864.80	0.175	7.56<	12,800,002	20170109083
B054<	89.97	0.10	2.332	81.80	868.06	0.175	5.55<	12,800,001	20170109083
B016<	80.00	-4.25<	3.136<	191.31<	367.48<	0.177	5.15<	12,799,946	20170109180
B016<	85.03	-3.95<	3.136<	191.81<	365.48<	0.177	4.80<	12,799,949	20170109180
B016<	89.97	-3.80<	3.138<	192.39<	363.20<	0.178	6.04<	12,799,951	20170109180