

Crystal Setup File Parameters

Run Name: jsc1112801-20170625

Print: All Operator:

Ref F: F @ 2

Run Start: 25-ÅÛÖÅ-2

Row A: Measured FL

Row B: Measured FL

Run Finish: 25-ÅÛÖÅ-2
S&A W2200 Rev: 6.6:

Start: B001 Stop: B006

Setup: JSC1112801-12.8MHZ-2017 85-95

Reference F: 12,800,000 Hz CL: 20.00 pF Power: 100.00 uW into 50.00 Ohms Measure: FL/T

	TEMP	FL	RR	C1	C0	Q	DLD2	FL
iAC	ppm	Ohms	fF	k	Ohms		MHz	
	2.00	100.00	0.22	5.07	20.00			
	-2.00		0.12	2.73	00.00			
B004<	85.02	0.85	106.09<	0.21	3.20	558<	0.53	12.800011
B004<	90.01	0.76	105.83<	0.21	3.20	558<	0.45	12.800010
B004<	95.02	0.61	105.73<	0.21	3.20	557<	0.78	12.800008
B005<	85.05	-0.49	66.30	0.19	2.92	998.	23.<	12.799994
B005<	89.98	-0.38	66.40	0.19	2.92	994.	49.<	12.799995
B005<	94.97	-0.39	66.21	0.19	2.92	994.	30.<	12.799995

20170502400 3
20170502400
20170502400 4
20130627269
20130627269
20130627269